

UDP

Rev1.0

2019-05-06

Lierda Science& Technology Group Co., Ltd



Lierda Science& Technology Group Co., Ltd



Lierda Science & Technology Group Co., Ltd.




Lierda Science & Technology Group Co., Ltd

	2
	3
	4
	5
	6
1.	7
2.	7
3.	7
4.	7
5.	8
5.1.	8
5.2.	Demo	8
5.3.	8
5.3.1.	8
5.4.	9
5.5.	9
6.	10
7.	10
8.	10

Lierda Science& Technology Group Co., Ltd

1.



2.

- TCP
-
- AT

3.

- Lierda NB86 EVK/NB86-G
- USB
- Eclipse

4.

Lierda Science & Technology

up Co., Ltd

5.

5.1.

ProjectLedFlashing

eclipse

Lierda NB-IoT


OpenCPU

DemoCode

5.2. Demo

Demo

5-1



5-1

5.3.

5.3.1.

• UDP

•

-

- AT



5.4.

Lierda NB-IoT

OpenCPU DemoCode

5.5.

AT

9600

Lierda Science& Technology Group

```
REBOOTING
□□?□?
Boot: Unsigned
Security B... Verified
Protocol A... Verified
Apps A..... Verified

REBOOT_CAUSE_APPLICATION_AT
Lierda
OK

*****
                NB86 EVK开发板例程——UDP数据收发
*****


利尔达科技集团<www.lierda.com>
LSD Science&Technology Co.,Ltd
杭州市余杭区文一西路1326号利尔达科技园
物联网开发者社区<http://bbs.lierda.com>
*****

Current network status is +CGATT:0
Current network status is +CGATT:0
Current network status is +CGATT:0
Current network status is +CGATT:0
AT+MLWEVTIND=0
AT+MLWEVTIND=3
Current network status is +CGATT:1
Current network status is +CGATT:1
DBG_INFO: cmd:AT+NSOST=1,54.222.172.6,7500,18,0F3836353335323033303436383132371151
result:
1,18
OK
```

6.

- UDP

7.



8.





Lierda Science & Technology Group Co.,